

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)
(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

1. Name of the Officer
2. Name of the School
3. Location with name of Education District/ Sub. District
4. Classification of Building as specified in column 4 of the application for fitness certificate and size.

BHAVANA P-U, ASSI. ENGINEER, KUNNAMKULAM MUNICIPALITY
HOLY CROSS CBSE ENGLISH MEDIUM RESIDENTIAL SCHOOL, ARTHAT
THRISSUR (C.DIST.), KUNNAMKULAM (SUB DIST)

Ground floor - 548 m²
First floor - 530 m²
Second floor - 530 m²
Total 1568 m²

5. Period for which the certificate is issued
6. Nature of defects , if any
 - a) Foundation and basement
 - b) Superstructure
 - c) Doors and Windows
 - d) Wood work wrought and put up
 - e) Roof
 - f) Flooring
 - g) Miscellaneous (Cracks, etc.)
7. Any major defects noticed which will render the building unsafe in any manner

2023-24

Nil

NO

8. Whether maintenance works have been done properly
9. Whether the structure is sound or not for conducting classes


YES
The structure is sound for conducting classes under normal weather conditions.

Note : 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

CERTIFICATE

certified that the school building was inspected by me on 04/07/23 and found to be fit / unfit to conduct classes, for the period 2023-24 for the reasons stated above.

Place: KUNNAMKULAM
Date: 04/07/2023



Roobas
NAGER
HOLY CROSS C.B.S.E. SCHOOL
ARTHAT - 680 521

Obw
12/7/23
ASST. ENGINEER
KUNNAMKULAM MUNICIPALITY
Assistant Engineer

[Signature]
PRINCIPAL
HOLY CROSS C.B.S.E. SCHOOL
ARTHAT - 680 521
KUNNAMKULAM

